




Muskingum Watershed
Conservancy District

PPE Checklist at a Glance Welding



See your Supervisor for the proper PPE. Make sure that PPE fits correctly and presents no additional safety hazard during use. Understand how to wear and maintain the PPE assigned for this task.

Shaded UV protective lenses shall be worn. Darkness of lenses determined by user and welding method used.

Clothing shall be worn to protect from burns such as long sleeves or welding jacket.